

Version history for HFB OPC Server / Driver Version 8.00

Build	Release date	Notes:
103	26.02.2021	Fixed issues: - !ConnState control tag provided a wrong value for FMS devices. New functions: - New control tag !FMSIndications: <device name=""> which provides the number of received FMS write indications.</device>
102	16.02.2021	Fixed issues: - Statistics field 'Unsolicited' renamed to 'Indications' Adaption to new INCOSOL Logo in Setup and Power Tool
101a	25.01.2021	Fixed issues: - Setup installed wrong/old Visual C++ redistributable package - Program exception when the HFB Power Tool was closed.
101	21.01.2021	New functions: - S5 PROFIBUS FDL support with CIFX50-DP or NetHOST DP as replacement for applications which use applicom® PCI1500PFB PROFIBUS cards with S5 FDL protocol header. For detailed information see
100	27.03.2020	Initial version for - PROFIBUS FMS and DP (Master or Slave) - PROFINET (IO Controller or IO Device) - EtherCAT (Master or Slave) - DeviceNet (Master or Slave) - CCLink (Slave)